

Facility Summary in GLACIER County in the City of BABB

Location: THRONSONS STORE
US HIGHWAY 89
BABB, MT 59411 GLACIER
Contact: Michael Thronson, (406) 732-5530

Sys Fac ID: 18-03871
Last Inspected On: 6/12/2014
Operating Permit Renewal Date: 9/3/2017

Owners/Operators: Thronsons Store, Owner (406)-732-5530 PO BOX 169
BABB MT 59411-0169
Michael Thronson, UST Class A Operator
Michael Thronson, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	26	12/31/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
4401			Double-Walled	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		5/28/2014	Manual Interstitial Monitor	MLLD Line Tightness Testing	
7,000		5/28/2014			
2	26	12/31/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
4402			Double-Walled	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		5/28/2014	Manual Interstitial Monitor	MLLD Line Tightness Testing	
3,000		5/28/2014			
3	26	12/31/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
4403			Double-Walled	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		5/28/2014	Manual Interstitial Monitor	MLLD Line Tightness Testing	
8,000		5/28/2014			

Facility Summary in GLACIER County in the City of BROWNING

Location: SCHOOL DIST 9 MAINTENANCE COMPLEX
BOUNDARY ST
BROWNING, MT 59417 GLACIER

Sys Fac ID: 18-03868

Last Inspected On: 7/3/2013

Operating Permit Renewal Date: 9/23/2016

Contact: Wayne Hall, (406) 338-2952

Owners/Operators: School Dist 9 Browning, Owner (406)-338-2952 PO BOX 610
BROWNING MT 59417-0610
Wayne Hall, Operator (406)-338-2952 742 BOARDING SCHOOL RD
BROWNING MT 59417
Wayne Hall, UST Class A Operator
Wayne Hall, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	29	11/29/1986	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
4130			Impressed Current	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		4/5/2013	Automatic Tank Gauging 0.2	Deferred	
8,000					
3	26	11/28/1989	Steel Clad	Steel	Flapper Valve (Auto Shutoff)
4131			Impressed Current	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		4/5/2013	Automatic Tank Gauging 0.2	Deferred	
8,000					

Facility Summary in GLACIER County in the City of BROWNING

Location: PARK CAFE AND GROCERY
3147 US HIGHWAY 89 HC 72 BOX 5
BROWNING, MT 59417 GLACIER

Sys Fac ID: 18-06436

Last Inspected On: 5/26/2015

Operating Permit Renewal Date: 12/31/2017

Contact: Keith Hilton, (406) 892-2121

Owners/Operators: Hilton Family Corporation, Owner	(406)-892-5589	PO BOX 2895 COLUMBIA FALLS MT 59912
Keith Hilton, Operator	(406)-250-1193	HC 72 BOX 5 BROWNING MT 59417
Keith Hilton, UST Class A Operator		
Keith Hilton, UST Class B Operator		

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	24	11/1/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
1382			None	None	Yes
Temporarily Out of Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
2,000		5/7/2015	TLS-350/Gilbarco EMC , Veeder Root		
2	24	11/1/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
1380			None	None	Yes
Temporarily Out of Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
12,000		5/7/2015	TLS-350/Gilbarco EMC , Veeder Root		
3	24	11/1/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
1381			None	None	Yes
Temporarily Out of Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
6,000		5/7/2014	TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in GLACIER County in the City of BROWNING

Location: TOWN PUMP INC BROWNING 2
US HIGHWAY 89
BROWNING, MT 59417 GLACIER

Contact: Trent Biggers, (406) 497-6700

Sys Fac ID: 18-08677
Last Inspected On: 12/28/2015
Operating Permit Renewal Date: 4/1/2019

Owners/Operators: Major Brands Distributing Imports Inc, Owner (406)-497-6700 PO BOX 6000
BUTTE MT 59702-6000

Charles A Armstrong, UST Class A Operator
Trent Biggers, UST Class A Operator
Don Edmisten, UST Class A Operator
Daniel Sampson, UST Class A Operator
Charles A Armstrong, UST Class B Global Operator
Trent Biggers, UST Class B Global Operator
Don Edmisten, UST Class B Global Operator
Daniel Sampson, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	20	6/1/1995	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
2467			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel		11/26/2012	Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000		11/30/2006	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
2	20	6/1/1995	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
2465			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline		11/26/2012	Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000		11/30/2006	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
3	20	6/1/1995	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
2466			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline		12/4/2009	Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000		11/30/2006	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in GLACIER County in the City of BROWNING

Location: TOWN PUMP INC BROWNING 2
US HIGHWAY 89
BROWNING, MT 59417 GLACIER

Contact: Trent Biggers, (406) 497-6700

Sys Fac ID: 18-08677
Last Inspected On: 12/28/2015
Operating Permit Renewal Date: 4/1/2019

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	20	6/1/1995	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4888			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel		11/26/2012	Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000		11/30/2006	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
13	20	6/1/1995	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
2463			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline		11/26/2012	Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000		12/1/2006	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
14	12	8/14/2003	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4859			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel		12/4/2009	Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
10,000		12/1/2006	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
15	12	8/14/2003	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4860			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel		11/26/2012	Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
5,000		12/1/2006	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in GLACIER County in the City of BROWNING

Location: SCHOOL DIST 9 TRANSPORTATION DEPT
829 SW BOUNDARY ST
BROWNING, MT 59417 GLACIER

Sys Fac ID: 18-12747

Last Inspected On: 7/3/2013

Operating Permit Renewal Date: 9/23/2016

Contact: Wayne Hall, (406) 338-2952

Owners/Operators: School Dist 9 Browning, Owner (406)-338-2952 PO BOX 610
BROWNING MT 59417-0610
Wayne Hall, Operator (406)-338-2952 742 BOARDING SCHOOL RD
BROWNING MT 59417
Wayne Hall, UST Class A Operator
Wayne Hall, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	23	7/1/1992	Cathodically Protected Steel	Flexible Plastic	High Level Alarm
1900		4/5/2013	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Impressed Current
Waste Oil		4/5/2013	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
1,000		9/8/2009			
2	23	7/1/1992	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
1898			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		4/5/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
8,000		9/8/2009			
3	23	7/1/1992	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
1899			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Diesel		4/5/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
8,000		9/8/2009			

Facility Summary in GLACIER County in the City of BROWNING

Location: GLACIER WAY CONVENIENCE STORE
STARR SCHOOL RD & DUCK LAKE RD
BROWNING, MT 59417 GLACIER

Sys Fac ID: 18-13768

Last Inspected On: 10/21/2014

Operating Permit Renewal Date: 12/20/2017

Contact: toney sitzman, (406) 338-7163

Owners/Operators: Pat Schildt, Owner	(406)-338-7163	PO BOX 1777 BROWNING MT 59417-1777
Violet Schildt, Owner	(406)-338-7163	PO BOX 1777 BROWNING MT 59417-1777
Charles Lafley, UST Class A Operator		
Harold Schildt, UST Class A Operator		
Charles Lafley, UST Class B Global Operator		
Harold Schildt, UST Class B Global Operator		

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	19	9/25/1996	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
3425		4/23/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline		7/9/2008	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
20,000			TLS-350/Gilbarco EMC , Veeder Root		
2	19	9/25/1996	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
3426		4/23/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel		7/9/2008	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
15,000			TLS-350/Gilbarco EMC , Veeder Root		
3	19	9/25/1996	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
3427		4/23/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline		7/9/2008	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
10,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in GLACIER County in the City of CUT BANK

Location: CUT BANK MUNICIPAL AIRPORT
2705 VALIER HIGHWAY
CUT BANK, MT 59427 GLACIER

Sys Fac ID: 18-00137

Last Inspected On: 8/20/2013

Operating Permit Renewal Date: 1/31/2017

Contact: Dan McCoy, (406) 873-8683

Owners/Operators: Cut Bank Airport Authority, Owner (406)-873-8683 2705 VALIER HWY
CUT BANK MT 59427

Roy Nollkamper, UST Class A Operator
David Ries, UST Class A Operator
Roy Nollkamper, UST Class B Operator
David Ries, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
8	18	11/1/1997	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
793		4/19/2013	None	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Jet Fuel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
12,000			TLS-300 , Veeder Root		
9	18	11/1/1997	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
794		4/19/2013	None	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Aviation Gas			Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
12,000			TLS-300 , Veeder Root		

Facility Summary in GLACIER County in the City of CUT BANK

Location: KENNY'S SUPER SERVICE
401 E MAIN ST
CUT BANK, MT 59427 GLACIER

Sys Fac ID: 18-00321

Last Inspected On: 8/20/2014

Operating Permit Renewal Date: 11/4/2017

Contact: Randy Fetters, (406) 873-2432

Owners/Operators: Kennys Super Service, Owner (406)-873-2432 401 E MAIN ST
CUT BANK MT 59427-3014
Randall Fetters, UST Class A Operator
Randall Fetters, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	30	6/13/1985	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
1471			None	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		3/12/2014	Automatic Tank Gauging 0.2	Deferred	
6,000			EECO 1500 , EMCO Electronics		
2	30	6/13/1985	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
1472			None	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		3/12/2014	Automatic Tank Gauging 0.2	Deferred	
6,000			EECO 1500 , EMCO Electronics		

Facility Summary in GLACIER County in the City of CUT BANK

Location: TOWN PUMP INC CUT BANK 2
510 W MAIN ST
CUT BANK, MT 59427 GLACIER

Sys Fac ID: 18-03417

Last Inspected On: 12/28/2015

Operating Permit Renewal Date: 4/1/2019

Contact: Trent Biggers, (406) 497-6700

Owners/Operators: Town Pump O Mat of Cut Bank Inc, Owner (406)-497-6700 PO BOX 6000
BUTTE MT 59702-6000

Charles A Armstrong, UST Class A Operator
Trent Biggers, UST Class A Operator
Don Edmisten, UST Class A Operator
Daniel Sampson, UST Class A Operator
Charles A Armstrong, UST Class B Global Operator
Trent Biggers, UST Class B Global Operator
Don Edmisten, UST Class B Global Operator
Daniel Sampson, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	22	3/1/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2459			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
10,000		12/2/2009	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
2	22	3/1/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2460			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000		12/2/2009	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
3	22	3/1/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2461			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000		12/2/2009	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in GLACIER County in the City of CUT BANK

Location: TOWN PUMP INC CUT BANK 2
510 W MAIN ST
CUT BANK, MT 59427 GLACIER

Sys Fac ID: 18-03417

Last Inspected On: 12/28/2015

Operating Permit Renewal Date: 4/1/2019

Contact: Trent Biggers, (406) 497-6700

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	22	3/1/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2462			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000		12/2/2009	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
7	15	5/1/2000	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4185			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
10,000		12/2/2009	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
8	15	5/1/2000	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4186			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
5,000		12/2/2009	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in GLACIER County in the City of CUT BANK

Location: BEN TAYLOR INC UST
201 BN INDUSTRIAL SITE
CUT BANK, MT 59427 GLACIER

Sys Fac ID: 18-04137

Last Inspected On: 4/24/2014

Operating Permit Renewal Date: 5/30/2017

Contact: Pete Barbie, (406) 873-2812

Owners/Operators: Ben Taylor Inc, Owner (800)-824-8366 PO BOX 810
SHELBY MT 59474-0810
Thomas Loch, UST Class A Operator
Thomas Loch, UST Class B Operator
Gail Mullennax, UST Class B Operator
Gregory Taylor, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
16	15	10/29/2000	Unknown	Flexible Plastic	
4241	Yes	4/18/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline			Deferred	Continuous Interstitial Monitor	
34,000			TLS-350/Gilbarco EMC , Veeder Root		
17	15	10/29/2000	Unknown	Flexible Plastic	
4242	Yes	4/18/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline			Deferred	Continuous Interstitial Monitor	
11,700			TLS-350/Gilbarco EMC , Veeder Root		
18	15	10/29/2000	Unknown	Flexible Plastic	
4243	Yes	4/18/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
12,500			TLS-350/Gilbarco EMC , Veeder Root		
19	15	10/29/2000	Unknown	Flexible Plastic	
4244	Yes	4/18/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
34,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in GLACIER County in the City of CUT BANK

Location: BEN TAYLOR INC UST
201 BN INDUSTRIAL SITE
CUT BANK, MT 59427 GLACIER

Sys Fac ID: 18-04137

Last Inspected On: 4/24/2014

Operating Permit Renewal Date: 5/30/2017

Contact: Pete Barbie, (406) 873-2812

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
20	15	10/29/2000	Unknown	Flexible Plastic	
4245	Yes	4/18/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
12,500			TLS-350/Gilbarco EMC , Veeder Root		
21	15	10/29/2000	Unknown	Flexible Plastic	
4246	Yes	4/18/2014	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
11,700			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in GLACIER County in the City of CUT BANK

Location: SIMONS BULK PLANT CUT BANK SATELLITE
813 E RAILROAD ST
CUT BANK, MT 59427 GLACIER

Sys Fac ID: 56-13775

Last Inspected On: 4/3/2014

Operating Permit Renewal Date: 7/30/2017

Contact: Pat Simons, (406) 434-2431

Owners/Operators: Simons Petroleum Inc, Owner (406)-434-2431 PO BOX 644
SHELBY MT 59474-0644
Pat Simons, UST Class A Operator
Joseph Pehan, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	18	10/31/1997	Bare Steel	Flexible Plastic	
1928	Yes	3/2/2012	None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Deferred	Automatic Tank Gauging 0.2	
12,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
2	18	10/31/1997	Bare Steel	Flexible Plastic	
1929	Yes	3/2/2012	None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Deferred	Automatic Tank Gauging 0.2	
8,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
3	03	3/1/2012	Unknown	Flexible Plastic	
5494	Yes	3/2/2012	None	Double-Walled	No
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Deferred	Automatic Tank Gauging 0.2	
11,800			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in GLACIER County in the City of CUT BANK

Location: TOWN PUMP OF CUT BANK #3
1119 E MAIN ST
CUT BANK, MT 59427 GLACIER

Sys Fac ID: 60-15144

Last Inspected On: 7/18/2015

Operating Permit Renewal Date: 12/11/2018

Contact: Trent Biggers, (406) 497-6700

Owners/Operators: Manhattan Holdings LLC, Owner (406)-497-6946 PO BOX 6000
BUTTE MT 59702-6000
Trent Biggers, UST Class A Operator
Trent Biggers, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	05	7/3/2010	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
5227			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
20,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
2	05	7/3/2010	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
5228			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
12,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
3	05	7/3/2010	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
5229			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Continuous Interstitial Monitor, Stat. Inventory Reconciliation, Approved Remote Monitoring	Stat. Inventory Reconciliation, Approved Remote Monitoring	
8,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in GLACIER County in the City of EAST GLACIER PARK

Location: SEARS MOTEL & GIFT SHOP
1023 HIGHWAY 49 N
EAST GLACIER PARK, MT 59434 GLACIER

Sys Fac ID: 18-03870
Last Inspected On: 5/26/2015
Operating Permit Renewal Date: 12/31/2017

Contact: Judy Jones, (406) 226-4432

Owners/Operators: Judy Jones, Owner (406)-226-4432 PO BOX 275
EAST GLACIER PARK MT 59434-0275
Judy Jones, UST Class A Operator
Judy Jones, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	25	9/28/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1453			None	None	Yes
Temporarily Out of Use			Not Required	Safe Suction	Not Applicable
Gasoline			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Not Listed	
2,000			Gilbarco EMC Basic , Gilbarco		
3	25	9/1/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1454			None	None	Yes
Temporarily Out of Use			Not Required	Safe Suction	Not Applicable
Gasoline			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Deferred	
2,000			Gilbarco EMC Basic , Gilbarco		

Facility Summary in GLACIER County in the City of EAST GLACIER PARK

Location: GLACIER WAY C-STORE #2
330 W CENTRAL AVE PO BOX 129
EAST GLACIER PARK, MT 59434 GLACIER

Sys Fac ID: 18-05813

Last Inspected On: 1/13/2015

Operating Permit Renewal Date: 3/13/2018

Contact: (406) 338-2575

Owners/Operators: Glacier Park 66 INC, Owner

(406)-338-2575

PO BOX 1609
BROWNING MT 59417

Tony Sitzmann, Operator

(406)-226-5504

PO BOX 129
EAST GLACIER PARK MT 59434-0129

Randy Livingston, UST Class A Operator

Michael Sherwood, UST Class A Operator

Troy Wilson, UST Class A Operator

Randy Livingston, UST Class B Operator

Michael Sherwood, UST Class B Operator

Troy Wilson, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	19	1/3/1997	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
4441			Double-Walled	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline		12/10/2008	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	ELLD Line Tightness Testing, Not Listed	
20,000		12/10/2008	Gilbarco EMC Basic , Gilbarco		
5	19	1/3/1997	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
4442			Double-Walled	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel		12/10/2008	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	ELLD Line Tightness Testing, Not Listed	
12,000		12/10/2008	Gilbarco EMC Basic , Gilbarco		

Facility Summary in GLACIER County in the City of EAST GLACIER PARK

Location: GLACIER WAY C-STORE #2
 330 W CENTRAL AVE PO BOX 129
 EAST GLACIER PARK, MT 59434 GLACIER
Contact: (406) 338-2575

Sys Fac ID: 18-05813
Last Inspected On: 1/13/2015
Operating Permit Renewal Date: 3/13/2018

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
6	19	1/3/1997	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
4443			Double-Walled	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline		12/10/2008	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	ELLD Line Tightness Testing, Not Listed	
12,000		12/10/2008	Gilbarco EMC Basic , Gilbarco		

Facility Summary in GLACIER County in the City of EAST GLACIER PARK

Location: BEAR TRACK TRAVEL CENTER
20958 US HIGHWAY 2
EAST GLACIER PARK, MT 59434 GLACIER
Contact: Clifford Fortune, (406) 226-5504

Sys Fac ID: 56-13933
Last Inspected On: 4/24/2013
Operating Permit Renewal Date: 6/30/2016

Owners/Operators: Fortune Development Corp, Owner (406)-226-5504 PO BOX 468
EAST GLACIER PARK MT 59434-0468
Clifford J Fortune, Operator (406)-226-5504 20958 HIGHWAY 2
EAST GLACIER PARK MT 59434
Julie Fortune, UST Class A Operator
Jim Fortune, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	16	6/1/1999	Unknown	Flexible Plastic	High Level Alarm
4068	Yes		Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Deferred	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
8,000					
2	16	6/1/1999	Unknown	Flexible Plastic	High Level Alarm
4069	Yes		Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Deferred	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
5,000					
3	08	9/14/2007	Concrete	Flexible Plastic	High Level Alarm
5126	Yes		Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Deferred	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
12,000					Yes

Facility Summary in GLACIER County in the City of SAINT MARY

Location: ST MARY LODGE
US HIGHWAY 89 ST MARY LAKE
SAINT MARY, MT 59417 GLACIER

Sys Fac ID: 18-01907

Last Inspected On: 6/12/2014

Operating Permit Renewal Date: 10/20/2017

Contact: Walter Kochansky, (406) 732-4431

Owners/Operators: Glacier Park Inc, Owner (406)-226-5631 PO BOX 147
EAST GLACIER PARK MT 59434
Glacier Park Inc, Operator (406)-226-5631 PO BOX 147
EAST GLACIER PARK MT 59434
Jon Noe, UST Class A Operator
Bob Hines, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	25	6/1/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
453			None	Secondary Containment Chase	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		5/29/2014	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
7,000		10/17/2007	TLS-350/Gilbarco EMC , Veeder Root		
2	25	6/1/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
454			None	Secondary Containment Chase	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Diesel		5/29/2014	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
3,000		10/17/2011	TLS-350/Gilbarco EMC , Veeder Root		
3	25	6/1/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
451			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		5/29/2014	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
15,000		10/17/2007	TLS-350/Gilbarco EMC , Veeder Root		
4	25	6/1/1990	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
452			None	Secondary Containment Chase	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		5/29/2014	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
15,000		10/17/2007	TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in GLACIER County in the City of SAINT MARY

Location: SAINT MARY RANGER STATION
NATIONAL PARK SERVICE
SAINT MARY, MT 59417 GLACIER

Sys Fac ID: 18-02745

Last Inspected On: 8/28/2013

Operating Permit Renewal Date: 12/22/2016

Contact: Del Zimmerli, (406) 888-7978

Owners/Operators: Glacier National Park, Owner (406)-732-7718 PO BOX 128
WEST GLACIER MT 59936-0128
Kenneth Kijewski, UST Class A Operator
Kenneth Kijewski, UST Class B Operator
Lori King, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	28	7/1/1987	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1221		12/20/2012	None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		8/28/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2	
12,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
6	00	10/1/2015	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
5620		10/28/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Deferred	
10,000			TLS-350/Gilbarco EMC , Veeder Root		Yes